

RECEIVING AND ESTIMATING REPORT

CUST NO: 051966 C.O.D.

COMMENTS

STEEL

CUSTOMER ORDER NO.

RECEIVED 25/91	DATE OPENED 10/30/91	DATE CODE DZ 9-75	SERIAL NUMBER A6206590	MODEL AND GRADE 700 270	BDL	ORDER R 91-21859
-------------------	-------------------------	----------------------	---------------------------	----------------------------	-----	---------------------

W/STUDS

HARD CASE

TO:
CARIS, NICK
P O BOX 2163
BUCKHANNON
USA

WV 26201

SHIP TO:

CARIS, NICK
P O BOX 2163
BUCKHANNON
USA

WV

26201

UNIT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 11/5/91	VIA UPS
-------------	--------------------	--------------------------------	------------	------------	----------------------	------------

R CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
----------	-----	-----------	-----	-------------	-------

CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"When putting a shell in the chamber, the gun jams"

FAULT: Cannot duplicate complaint - firing pin could not be made to fall fully cycling bolt. However, it was noted that trigger assembly had been adjusted out of factory - trigger pull below our minimum spec (at measured to be 2 3/4 pounds) trigger retraction was not consistent, because of light pull - rear lift 0.007"

We can re-adjust trigger assembly to heavier pull weight, or, offer to install new trigger assembly at 1/2 normal cost, as a gesture of good-will, if this will better restore confidence in the rifle.

REPAIRMAN JTR	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PS01568