

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL JJM	CUSTOMER ORDER NO.		DATE RECEIVED 06/05/91		DATE OPENED 06/10/91	DATE CODE BU 1-71	SERIAL NUMBER 6400232	MODEL AND GRADE 700 243 BDL	ORDER R 91-12162
ACCESSORIES W/STUDS									

L/REAR SIGHT

FROM:	SHIP TO:
CARLS RELOADING CENTER 435 EAST 3RD NORTH RICHFIELD UT 84701	CARLS RELOADING CENTER 435 EAST 3RD NORTH RICHFIELD UT 84701

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: *fires when safety is moved.*

MAIN FAULT: *Could not duplicate complaint after many attempts! However, removal of action from stock revealed trigger assembly had been tampered with by the factory. Sealant on adjusting screws was not original. Overtravel had been altered and was insufficient. Trigger pull 3 pounds; run-off .0075".*

PARTS: *We can either re-adjust over-travel and return rifle as is, or we can install a new trigger assembly at \pm normal cost as a gesture of good-will, if it will better restore confidence in the rifle.*

REPAIRMAN HEB	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE