

Remington Arms Service
TO 14 Hoefler Avenue
Iliou, New York 13357

FROM

CARL'S RELOADING CENTER

435 East 3rd North
RICHFIELD, UTAH 84701
Phone (801) 896-6871

SUBJECT: Gun Repair

DATE: 5/21/91

FOLD ↑ My customer claims that the enclosed 700 BDL
243, SN 6400232, fires when the safety is moved
to fire. This happens on ^{very} rare occasion.

I am afraid of this gun so I am sending
it to you for factory testing and adjustment.

Sincerely,

PLEASE REPLY TO

→ SIGNED

Carl J. Thurgood.

REPLY

DATE:

SIGNED

Item # F270 Grayac, P.O. Box 2944, Hartford, CT 06104-2944
© Wheeler Group, Inc., 1982

THIS COPY FOR PERSON ADDRESSED

return rifle to us, we can install a new
trigger assembly at $\pm$ normal cost,
as a gesture of good-will, if it will
better restore confidence in the
rifle.

REPAIRMAN

GALLERY TESTER

PROOF

DATE

CLEAN

DATE

TEST

DATE

TARGET

DATE

PATTERN

DATE

OFFICE COPY

RD6925 REV. 7/90

PS01575