

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL JJM	CUSTOMER ORDER NO.					
DATE RECEIVED 01/31/91	DATE OPENED 02/07/91	DATE CODE AR 3-68	SERIAL NUMBER 335193	MODEL AND GRADE 700 30-06 BDL		ORDER R 91-03891
ACCESSORIES W/STUDS						

FROM:	SHIP TO:
COGNEVICH, LOUIS M, JR 568 W MARLIN CT GRETN LA 70056	COGNEVICH, LOUIS M, JR 568 W MARLIN CT GRETN LA 70056

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

--	--	--	--	--	--

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: *"If the trigger is pulled prior to releasing the safety, when the safety is released the gun will discharge".*

MAIN FAULT: *Complaint could be duplicated. Trigger assembly has been adjusted outside factory. Additionally, trigger parts were coated with a varnish type substance which appeared to be solidified lubricant. This combination resulted in the malfunction noted.*

PARTS	<i>Rifle was misplaced by Product Service, causing delay in loading.</i>					
	<i>Per phone call to customer 8/28/91, replace trigger assembly at no charge, as a gesture of good-will.</i>					
	<i><u>Do not charge handling or return shipping.</u></i>					
REPAIRMAN LEW	PROOF	CLEAN	TEST	TARGET	PATTERN	
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	

ST=KL

RD6925 REV. 7/90

PS01610