

Remington.

DUPOND

RECEIVING ESTIMATING REPORT
REMINGTON ARMS COMPANY, Inc.

SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS

MILTON, NEW YORK 13357

RTS: (315) 895-7493, REPAIRS: (315) 895-7791

PAGE 1

11/20/89

DATE:

SOLD TO

REPAIR ORDER NO.: 8925770

SHIPPED TO

REPAIR ORDER NO.

8925770

CARMINE P CONTI
89 RICCIARDONE AVE
TORRINGTON CT 06790CARMINE P CONTI
89 RICCIARDONE AVE
TORRINGTON CT 06790

WE ACKNOWLEDGE RECEIPT OF THE ITEM(S) DESCRIBED BELOW.

THE NECESSARY CORRECTIONS ARE BEING PERFORMED WITHOUT CHARGE AND PREPAID SHIPMENT WILL BE MADE IN ABOUT 4 WEEKS.

WE KNOW YOU WILL FIND THE REPAIR TO BE COMPLETELY SATISFACTORY AND IF WE CAN HELP YOU IN ANY OTHER WAY, PLEASE LET US KNOW.

1700 0270WIN 30L SERIAL NUMBER: A6445396

CUSTOMER REQUEST:

FIRES WHEN SAFETY MOVED FORWARD

MAIN FAULT FOUND:

EXCESSIVE LUBRICATION IN TRIG ASSEMBLY

1 0026345

TRIGGER ASSEMBLY RH

EXCESSIVE LUBRICATION FOUND ON TRIGGER ASSEMBLY AND ACTION. COULD NOT DUPLICATE ALLEGED COMPLAINT. REPLACE TRIG ASSEMBLY AT N/C AS A GESTURE OF GOODWILL. APPROVAL BY MR CONTI PER PHONE 11/16/89.

NOTE: TEST W/SLAVE STOCK- CUSTOMER HAS REPLACEMENT, HE IS AWARE THAT STOCK RETURNED IS CRACKED. CLEAN, TEST

*

TOTAL REPAIR CHARGE
TAXESINSURANCE
PARCEL POSTTOTAL
CHARGES

NO CHARGE

ATTENTION

DATE

1925 REV. 7