

RECEIVING AND ESTIMATING REPORT

COMMENTS

R 93-1366

INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED

06/04/93

DATE OPENED

06/07/93

DATE CODE

DQ 9-73

SERIAL NUMBER

A6637321

NEW SERIAL NUMBER

MODEL AND GRADE

700 243

ADL

ACCESSORIES

W/STDS

W/STDS

SCOPE BASE

L/REAR SIGHT

FROM

DAVID C ROSE GUNSHOP
12521 W HWY 162
FARMINGTON

AR 72730

SHIP TO:

DAVID C ROSE GUNSHOP
12521 W HWY 162
FARMINGTONAR
72730

CUST NO: 000184 ILIONL

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

6-30-93

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Upon receipt could not find function. Trigger group frozen solid to trigger housing from an unknown heavy quarry substance. Bolt stop action also bound up. Little metal good cleaning. Mfg. error.

COMMENTS

Replace complete trigger assembly at 1/2 normal replacement cost. It gives up good work, & clean action. Go ahead.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE