

RECEIVING AND ESTIMATING REPORT

DATE JUN 37/13/92	CUSTOMER ORDER NO. JUN 07/23/92	DATE CODE LW 2-72	SERIAL NUMBER 6525056	NEW SERIAL NUMBER	MODEL AND GRADE 700 270	ORDER R 92-14920
CLASSIFICATION H/STUDS		SCOPE BASE	ADL			

SHIP TO: DAVIS, DALE HC 82 BOX 568 ATOKA OK 74525	CUSTOMER NO: 064019 C.D.D.
--	----------------------------

QUANTITY 1	ACCOUNT NUMBER INC	WRITE- ☐ CLEAN/TEST	FROM DATE	ESTIMATED	VIA UPS							
CONDITION NEW LIGHTLY WORN WORN VERY WORN UNREPAIRABLE DARNED	<table border="1"> <tr><td>REPAIR CHARGE</td></tr> <tr><td>EXCISE</td></tr> <tr><td>TAX</td></tr> <tr><td>INSURANCE</td></tr> <tr><td>UPS</td></tr> <tr><td>PARCEL POST</td></tr> <tr><td>TOTAL</td></tr> </table>				REPAIR CHARGE	EXCISE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL	
REPAIR CHARGE												
EXCISE												
TAX												
INSURANCE												
UPS												
PARCEL POST												
TOTAL												

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
LE	A1					
GER GROUP						
T ASSY.						
REL ASSY.						
ASSY.		B5		D2	E3	F4
ID			C1	D3	E4	F5
AL			C2			

FAULT: Trigger assembly contaminated with WD-40 (per owner).
 in spite of gun being disassembled and cleaned - not moving freely -
 right slide not moving freely in forward position.

COMMENTS	
As per owner's request, trigger assembly was cleaned with WD-40. Charge handling & return shipping.	
REPAIRMAN	PROOF
GALLERY TESTER	DATE
CLEAN	DATE
TEST	DATE
TARGET	DATE
PATTERN	DATE

OFFICE COPY

RECEIVED MAY 1 1992