

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs
Fax

800-243-9700
336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number	Description/Serial Number	Date Received -
RE00046705	C6368812	6/14/2002
Account # - R-	Model 700 Center Fire Caliber: 308 PSS	Estimate Date - 5/17/2002
		Current Date - 6/17/2002

Customer
DEPUTY PETER TARABORELLI
SRT ARMORER
1001 OLD TOMOKA RD
ORMOND BEACH, FL 31176 US

Return To
DEPUTY PETER TARABORELLI
SRT ARMORER
1001 OLD TOMOKA RD
ORMOND BEACH, FL 31176 US

Phone (H) (386)-676-4182
Phone (W) (386)-257-2499

Fax
Email

Problems

Reported	Found
M992 FIRED ON CLOSING	M112 HEADSPACE IS EXCESSIVE M123 FORWARD TO PRODUCT SERVICE FO

Technician's Comments

ProblemNotes All three settings altered. Sear engagement screw backed out creating an unsafe condition. Quote for a new trigger assembly and cleaning action at 1/2 normal charges as gesture of goodwill. FLS 5/15/02.

Parts and Labor


Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	N
F93712	700 EXTRACTOR REG (7400;710)	1	N
F94369	700 BOLT ASSB MAX S/A	1	N
Part Total:		<u>3</u>	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	N
4000117	GR-PROOF	1	Y
4000119	GR-TEST	1	N
Service Total:		<u>2</u>	

15 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFER AVE
MILTON NY 13357

SHIP

TO: DEPUTY PETER TARABORELLI
SRT ARMORER
1001 OLD TOMOKA RD
ORMOND BEACH FL 32176




FL 320 2-02



UPS GROUND

TRACKING #: 1Z 114 813 03 1189 8123



BILLING: PREPAID

INV#: RE00046705

ASC 3.70 J69K/J64K 14.0 01/2002