

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00051976 Account # - R- Customer DUNNS SPORTING GOODS 3808 WEST CLAY SAINT CHARLES. MO 63301 US Phone (H) (636)-916-0242 Phone (W)	Description/Serial Number 6436010 Model 700 Centre Caliber: 6 MM BDL	Repairman - Chuck Dekanek Date Received - 9/16/2002 Estimate Date - Current Date - 9/18/2002 Return To DUNNS SPORTING GOODS 3808 WEST CLAY SAINT CHARLES. MO 63301 US Fax Email
---	--	---

Reported	Found
M238 CLEAN & INSPECT M992 UNINTENTIONAL FIRING	M123 FORWARD TO PRODUCT SERVICE F

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:					
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000119	GR-TEST	1	1	0	Y
4000294	GR-CHECK TPA	1	1	0	Y
Service Total:					
		22	22	0	

Problem/Notes Action and trigger assembly dirty. Replace complete trigger assembly and clean action. charge 20.00 per DJS.					
Repairman	Proof	Clean	Test	Target	Pattern
Galler Tester	Date	Date	Date	Date	Date

14 LBS 1 OF 1


COD

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

DUNNS SPORTING GOODS
3808 WEST CLAY
SAINT CHARLES MO 63301




MO 630 9-02



UPS GROUND

TRACKING #: 1Z 114 813 72 1194 5568



BILLING: P/P
COD \$20.00

INV#: RE00051976

ASC 05.00 J69X/J64X 16.0A 01/2002