

Repair Order Number



Repair Order Number RE00053000	Description/Serial Number A6560082	Repairman - Robert Frink Date Received - 9/26/2002
Account # - R-	Model 700 Center Fire Caliber: 3006 ADL	Estimate Date - Current Date - 9/30/2002
Customer WILLIAM DUNDON 2690 BOSHART RD LOWVILLE, NY 13367 US	Return To WILLIAM DUNDON 2690 BOSHART RD LOWVILLE, NY 13367 US	
Phone (H) (315)-376-8417 Phone (W)	Fax Email jbdundon@citlink.net	

Reported		Problems		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F		

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Total:					
Could not duplicate.					
Dirty residue in TA.					
Quote \$20 for new TA and					
cleaning action under bolt lock					
modification program.					
FLS 10/1/02					

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date