

Fire Arm not updated

Update using current procedure

Could not duplicate concern - rifle
Action sluggish.

FCS 4/24/00

Serial
Number:

40336

Model: 600



RE00008522