



DESERT GUNS

210 W. Broadway St.
Hobbs, New Mexico 88240
(505) 391-9090

G. Mark Stone

could not duplex
trig. assm. set screws
have been altered. Replace
TPA complete + check over at
1/2 msp. Quote

SEPT. 21, 2004

RAC

ILION, N.Y.

PRODUCT SERVICES DIVISION

DEAR SIR OR MADAM,

ENCLOSED IS A MODEL 700,
SN F6214106, THAT MY CUSTOMER
SAYS HAS DISCHARGED THREE TIMES
WHILE HE WAS CLOSING THE BOLT.

WE DID NOT ORIGINALLY SELL
THIS FIREARM TO HIM, NOR HAVE
WE MADE ANY ADJUSTMENTS WHATSOEVER
TO THIS RIFLE.

I AM MERELY SHIPPING THIS
TO YOU AS A SERVICE TO MY CUSTOMER.
PLEASE REPAIR.

Number: **F6214106**

SINCERELY,

Model: **700**

G. M. Stone



RE00085743