

Remington

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00085956	Description/Serial Number G6219479	Repairman - Chuck Dekanek Date Received - 10/7/2004
Account # - R-	Model 700 Center Fire Caliber: 308 BDL VARMIT W/BI POD	Estimate Date - Current Date - 10/13/2004
Customer DANE COUNTY SHERIFF 5184 STATE ROAD 19 ATTN ARMORER JAMES HITT WAUNAKEE, WI 53597 US		Return To DANE COUNTY SHERIFF 5184 STATE ROAD 19 ATTN ARMORER JAMES HITT WAUNAKEE, WI 53597 US
Phone (H) (608)-849-2664 Phone (W)	Fax (608)-849-2666 Email hitt@co.dane.wi.us	

Reported		Problems Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRES W/O TOUCHING TRIGGER		

Material #		MaterialDesc		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
F26345		700 TRIG ASSB RH		1	1	0	Y
Part Total:				1	1	0	
Service							
4000294		GR-CHECK TPA		1	1	0	Y
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000119		GR-TEST		1	1	0	Y
Service Total:				2	2	0	

ProblemNotes Could not duplicate. Replace trigger assembly at no charge to restore confidence in rifle.					
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date