

11 Oct 04

Remington Arms

Re: Model 700

S/# A6219548.

Please replace trigger assembly
so that weapon can be loaded on
"S" or safe position.

This rifle has misfired while
chambering.

William L. Donay
6220 Island Ford Rd
Hansen, Ky 42413
270-322-8537.

Please call for credit card #
for payment.

Serial
Number:

A6219548

Model: 700



RE00086482

6482

1008
4040

could not duplicate
hit new TPA under bolt lock
safety program for \$20.00 quote