

Dennis Annetta
Remington Arms Co.

1-17-95

Gentlemen;

Please check trigger group, safety, rear
as this rifle discharged when safety was
pushed to fire position.

I believe that rust in the trigger
group was the cause. A fellow hunter
was shot in the foot when this occurred.

Please R/R and inform me of your
findings.

Thank you for your concerns

Larry Doran

LARRY DORAN
17560 SLATER Rd
N. Ft MYERS FL
33917
813-543-9343