



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00083804	Description/Serial Number G6280312	Repairman - Robert Frink Date Received - 8/18/2004
Account # - R-	Model 700 Center Fire Caliber: 300 BDL	Estimate Date - Current Date - 8/25/2004
Customer DOUGS SPORT SHOP HAWES PLAZA 220 N MAIN STREET MOOREFIELD, WV 26836 US		Return To DOUGS SPORT SHOP HAWES PLAZA 220 N MAIN STREET MOOREFIELD, WV 26836 US
Phone (H) (304)-538-6496 Phone (W)		Fax Email

Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRES WHEN BOLT IS WORKED		

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000119	GR-TEST	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000118	GR-CLEAN	1	1	0	Y
Service Total:		2	2	0	

ProblemNotes	Could not duplicate. Replace complete trigger assembly and clean action to restore confidence in rifle.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date