

Supry, Fred L.

To: gderrick@cricpa.com
Subject: Model 700 concern

Dear Mr. Derrick,

We examined the rifle that you returned for firing on bolt closing. During our examination we were unable to get it to duplicate your concern; however, we did notice a very sluggish return of the trigger under the sear after firing. It is our opinion that this may have contributed to the incident that you experienced.

To correct that, we are cleaning the action and installing a complete new trigger assembly. Once the work is completed the rifle will be test fired, and then a final inspection done before returning the rifle to you. This work will be completed at no cost to you. We wish you many years of enjoying the shooting sports.

Fred Supry
Product Service Manager
AFTE Technical Advisor
Remington Arms Company
14 Hoefler Avenue
Ilion, NY 13357

Office: 315-895-3606
Fax: 315-895-3661

fred.supry@remington.com