

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-24429

INITIAL
JJM

CUSTOMER ORDER NO.

ATTN J STEKL

DATE RECEIVED
11/22/91

DATE OPENED
11/27/91

DATE CODE
BD 1-83

SERIAL NUMBER
7600607

NEW SERIAL NUMBER

MODEL AND GRADE
7 243

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

RUD, DELBERT
P O BOX 212
DILWORTH
USA

MN 56529

SHIP TO:

RUD, DELBERT
P O BOX 212
DILWORTH
USA

MN 56529

CUST NO: 053736 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Cannot duplicate complaint. However, disassembly of rifle revealed bottom of barrel and piston dripping wet with oil. Trigger assembly has been adjusted outside factory - 1) Trigger pull measured at 2 pounds (well below minimum spec.) trigger situation is not positive 2) over-travel is insufficient. The excessive oil, non-positive trigger situation coupled with cold temperatures could conceivably cause a problem. Ser-left = 011".

PARTS

COMMENTS

re-adjust and clean present trigger assembly, if possible or we can offer a new trigger assembly at 5000.00 cost, as a gesture of good-will, if it will better restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/91

PS01849