

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-28130

INITIAL
LCS

CUSTOMER ORDER NO.

ATTN JIM STEKL W/ 1 LIVE ROUND

DATE RECEIVED
12/11/91

DATE OPENED
12/16/91

DATE CODE

SERIAL NUMBER
6534020

NEW SERIAL NUMBER

MODEL AND GRADE
600 308

MOHAWK

ACCESSORIES W/STUDS

L/SIGHTS

SCOPE BASE

FROM:

DONBROWSKI, DAVE
1126 BUCHANAN RD
KAUKAUNA
USA

WI 54130

SHIP TO:

DONBROWSKI, DAVE
1126 BUCHANAN RD
KAUKAUNA
USA

WI 54130

CUST NO:009461 C.D.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

B3

BARREL ASSY.

REC. ASSY.

B5

WOOD

C1

D3

E5

F5

METAL

C2

1) "It has mis-fired several times" and 2) "The rifle fired after taking the safety off."

MAIN FAULT

Cannot duplicate complaint. However, trigger assembly has been completely mis-adjusted out of factory - 1) Trigger pull heavy (9 lbs) 2) over travel excessive, 3) rear engagement insufficient. We have no way of knowing what caused original problem, since trigger assembly is too long in the same condition.

PARTS

COMMENTS

Offer replacement to trigger assembly at normal cost, as gesture of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/9

PS01854