

# RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 94-01826

INITIAL  
J.J.M.

ATTN DENNIS SANITA CALL TAG  
NO CORR

DATE RECEIVED 01/13/94	DATE OPENED 01/14/94	DATE CODE DY 9-74	SERIAL NUMBER 6784235	NEW SERIAL NUMBER	MODEL AND GRADE 700 25-06	RDL
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS		

FROM:

DOCKERY, BERTEL  
RT 3 BOX 746  
GROESBECK

TX 76642

SHIP TO:

DOCKERY, BERTEL  
RT 3 BOX 746  
GROESBECK

TX

76642

CUST NO: 090636 C.D.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
UN CONDITION <input type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED					REPAIR CHARGE 25.00 EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
YCLE	A1	B1				
RIGGER GROUP		B2			E1	F1
OLT ASSY.		B3			E2	F2
ARREL ASSY.		B4			E3	F3
EC. ASSY.		B5		D2	E4	F4
OOD			C1	D3	E5	F5
ETAL			C2			
IN FAULT						

*Left mfg 1974. Upon receipt, unable to duplicate customer concern. Examination revealed that the action is binding with a heavy tummy substance. Bolt stop release will not return. Trigger assembly faulty.*

COMMENTS

*Repair complete trigger assembly and clean action at 1/2 normal replacement cost, superior of good work.*

*6 A/S*

*1/15/94*

*Go ahead - per phone 1/15/94 with Mr. [unclear]*

REPAIRMAN	PROOF	CLEAN	TEST	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE

OFFICE COPY

BOOK RE 112

PS01861