

Fred Drischler

114 Clarks Chapel Rd.
Nassau, NY 12123
(518)-479-7607

3.5

9/73

April 11, 2005

Remington Arms Company, Inc.
Ilion Firearms Plant
Attention: BL Safety Program
14 Hoefler Avenue
Ilion, NY 13357

Dear Sir or Madam:

Please find enclosed a model 700 Remington in .243 caliber, sn# 6671443. I am returning the firearm per your bolt lock safety modification program. The gun misfired four times during the 2004 hunting season while switching from safe "S" to "F" fire, the gun went off. Please make proper adjustments to the firearm.

Sincerely,

Fred Drischler



could not duplicate concern
Trigger set screws altered. Replace
TPA under bolt lock program
For \$20.00 quote

Serial
Number:

6671443

Model: **700**



RE00096154

PS01960