

RECEIVING AND ESTIMATING REPORT

COMMENTS

BOTTOM HALF OF MTS ONLY

INITIAL JJM	CUSTOMER ORDER NO.						
DATE RECEIVED 01/10/90	DATE OPENED 01/16/90	DATE CODE KO 5-77	SERIAL NUMBER A6449916	MODEL AND GRADE 700 7MMAG		BDL	ORDER R 90-01527
ACCESSORIES W/STUDS		SCOPE BASE L/REAR SIGHT					

FROM:

DAVID D'ISIDORO
RD 1
BOX 201
SMOCK PA 15480

SHIP TO:

DAVID D'ISIDORO
RD
BOX 201
SMOCK

PA

15480

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"It has a delayed action when fired and it discharges when the bolt is closed".

MAIN FAULT

Customer's complaint was duplicated with rifle in as-received condition. Subsequent disassembly of rifle revealed semi-safety cam sticking to housing side plate. Inside of assembly contaminated with gummy sticky residue (also present on bolt stop).

ARTS

1) Per phone call to customer 1/23/90 - replace trigger assembly at no-charge, as good-will gesture.

2) Charge \$10.00 handling and return shipping.

1/23/90
JLM

DEPATRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

RD6925 REV. 6/88

PS01984