

25 Sept 01

Ross G. Dolezal
35940 County Highway 6
Redwood Falls, MN 56283-2568

507-641-5315

(please leave message)

Serial
Number:

6784656

Model: 700



RE00033566

Hi -

→ Please inspect my 700 Remington. The rifle
fired twice as I took the weapon off safe.

Once while a round was in the chamber,
once when the chamber was empty. Both
times when the temperature was 15°-20°F.

→ Yes, I had tampered with the trigger

before this happened. I understand that
a new trigger assembly may be necessary.

If so, I would like to be contacted if
there are any options in trigger quality,
models, features, etc. This rifle has not
been fired ~~a~~ a-whole-lot for a 27-28

year old firearm.

10/8/01
Replace trigger assem at 1/2 MSP
Thank you,
Ross