

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-21149

INITIAL FPS	CUSTOMER ORDER NO. 33145				
DATE RECEIVED 10/07/92	DATE OPENED 10/13/92	DATE CODE OD 7-83	SERIAL NUMBER B6470503	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06 BDL
ACCESSORIES W/STUDS		SCOPE BASE			

FROM:

DUNBARS GUN REPAIR INC
509 1/2 UNION STREET
SPARTANBURG SC 29301

SHIP TO:

DUNBARS GUN REPAIR INC
509 1/2 UNION STREET
SPARTANBURG SC 29301

CUST NO: 006084 ILION

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	R1				
TRIGGER GROUP						
BOLT ASSY.		P2				
BARREL ASSY.		R1				
REC. ASSY.		R1				
WOOD			G1	D1	I3	
METAL			G2			

MAIN FAULT

Sent to J Steel
Cannot describe complaint. However, disassembly of trigger group and underneath receiver an exploded trigger group. Inside of trigger assembly contaminated with dirt and oil. Even in above condition, the rifle would not fire to malfunction.

Trigger pull 4 1/2 pounds; clean - lift a 011"

PARTS	COMMENTS
	1) Clean receiver out of barrel of receiver 2) After following operation: a) Clean & reassemble trigger assembly b) install new trigger assembly at normal cost, as a guarantee of good will, if that will better his confidence in rifle 3) Give new trigger guard assembly at normal cost, as good will given.
REPAIRMAN	PROOF
GALLERY TESTER	DATE
CLEAN	TEST
TARGET	PAT1
DATE	DATE

OFFICE COPY

RD6925 REV

PS02025