

File Number: 19078		Arms Service number: 67109	
Last Name: DARRYL S LOCK-N-GUN		First Name:	
Street: 726 WASHINGTON AVENUE		City: GREENVILLE	
State: MS	Zip: 38701	Home Ph: 662-332-7718	
Work Ph:	Product Type: F	F A T O	
Type Concern: S	PI PD P S	Concern Code: 1008	
Concern: FIRED ON BOLT CLOSING			
Cause Code: 4040	Cause: OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To: SUPRY	Classification: UND	UNJ UNC UND J	
Settlement Detail: SPECIAL PRICE REPAIRS	Settlement Amount:		\$0.00
Date Opened Rem: 7/8/2003	Date Opened by P/S: 7/14/2003	Caliber:	50
Date of Incident:	Date Closed: 7/16/2003	Bullet Weight:	
Date to Analysis:	Date from Analysis:	Manufacturer:	
Model: 700	Serial: ML002216	Date Code: CQ	Date Mfgd: 4/4/1996
RAMAC: 700	Litigation: <input type="checkbox"/>	PreLitigation: <input type="checkbox"/>	Obsolete: <input type="checkbox"/>
Custody:	Comments: As received the firing pin would follow down - TA screw settings altered. Cleaning rod bracket rusted (cleaning rod will not slide through properly.) Install new TA at 1/2 normal charges, clean rifle. Send quote or call as requested. Repair and shipping documents 8/6/03.		
Time of Modification: 10:59:39 AM			
Date of Modification: 7/16/2003			