



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00067109	Description/Serial Number ML002216	Repairman - Robert Frink Date Received - 7/21/2003
Account # - R-	Model 700ML Center Fire Caliber: 50 SS	Estimate Date - 7/16/2003 Current Date - 7/22/2003
Customer DARRYLS LOCK N GUN 726 WASHINGTON AVE GREENVILLE, MS 38701 US	Return To DARRYLS LOCK N GUN 726 WASHINGTON AVE GREENVILLE, MS 38701 US	
Phone (H) (662)-332-7718 Phone (W)	Fax (662)-335-9242 Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M991	FIRES WHEN BOLTED		

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F201880	700 ML WEATHER SHROUD	1	1	0	Y
F99294	700 ML SS TRIG ASSB	1	1	0	N
Part Total:		2	2	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000118	GR-CLEAN	1	1	0	N
Service Total:		1	1	0	

ProblemNotes	Trigger assembly screw settings altered. Parts dirty and rusted, poorly maintained. Install new trigger assembly at 1/2 normal charges. Quote. FLS 7/14/03.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date