

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-03195

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/20/92

01/27/92

RF 11-85

B6756272

700 270

MTN

ACCESSORIES

W/STUDS

FROM:

DELOACH, JOEL K
RT 1 BOX 101
HAMPTON

TN 37658

SHIP TO:

DELOACH, JOEL K
RT 1 BOX 101
HAMPTON

TN
37658

CUST NO: 056979 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

2-18-92

UPS

CONDITION

NEW

SLIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

COLE

A1

B1

TRIGGER GROUP

B2

SLT ASSY.

B3

BARREL ASSY.

B4

EC. ASSY.

B5

WOOD

C1

ETAL

C2

E1

E2

E3

E4

E5

F1

F2

F3

F4

F5

IN FAULT

*Trigger assembly is contaminated with a gunning residue
substance - internal trigger parts not moving freely nor properly
ear - safety cam is sticking to side plate of trigger assembly
It has not been properly maintained
user pull 5 rounds, rear left .012"*

RTS

COMMENTS

*Offer to clean present trigger
assembly, if possible. If not possible,
offer replacement assembly at expense
of user, as a gesture of good-will.*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

DE

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/91

PS02035