

Date: 8/26/05

By: Bruce Travis

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Ronnie Duet

R.E. Number: 100092

Reason for inspection: FSR

FIREARM

Manufacturer: Rem. Model: 700

Serial Number: ML061771 Date of Manufacture: 3/97

Overall external condition: FAIR

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: After M.I.T., Nipple + F.P.

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: connector Broken

Headspace: —

Function evaluation:

Test firing results (if applicable): _____

DISPOSITION

CONNECTOR BROKEN, Replace TPA & check over
completely A + 14/c #230145

ADDITIONAL COMMENTS