

To whom IT MAY Concern.

The Gun has a Big problem! When you Pull the trigger the gun will NOT Fire. There is a 2 To 3 second. delay from the time you pull the trigger, till the gun Fires.

I TOOK the gun To a gun-smith in the Beckley, W.Va. area on 12/1/03. He told me that I seemed To be ON the trigger Having (R.T.) would NOT work on the

Serial Number: **7685074**

Model: 7



RE00073979

I need To send the gun for Repair.

I need a estimate on how much it will cost To have the STALK.

Refinished - 304-465-1645

Upon receipt we could not duplicate the reported problem

12/15/03. Big Game Company

Pruned with a heavy brown sticky substance. Poor Maintenance

Replace trigger assembly at 1/2 MSP

EARL DILLON.

211 LAVENDER ST

OAK-HILL, W.Va

25901

73979

Auto Code

EM 10/02

Go ahead