

## RECEIVING AND ESTIMATING REPORT

COMMENTS

Product  
ServiceORDER  
R 98-24197

INITIAL CUSTOMER ORDER NO

JJM

ENHANCED

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/13/98

11/16/98

AR 3-97

T6232644

700 260

SS/DM/SYN

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

DORN RAYMOND E.  
22712 W BALDWIN RD.  
BANNISTER

MI 48807

DORN RAYMOND E.  
22712 W BALDWIN RD.  
BANNISTERMI  
48807

CUST NO: 198080 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

230145

WRITE ☐

PROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☒ NEW  
☐ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D2

E4

F4

METAL

C2

D3

E5

F5

MAIN FAULT

Information received that there was rust inside the  
trigger, rusting the trigger to the trigger pin. Rusty from  
Walther's source.

PARTS

COMMENTS

Repair the complete  
trigger assembly at no charge.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 7/97

PS02058