## Remington.

## TRACKING DOCUMENT

## Repair Order Number



Repair Order Number

RE00077413

A6345953

Date Received · 3/15/2004

Herb Brown

Account # - R-

Model 600 MOHAWK Center Fire Caliber: 243

Description/Serial Number

Estimate Date -

Current Date - 3/26/2004

Customer

D AND D OUTDOOR SPORTS

UNION. MO 63084 US

7133 HWY 47

D AND D OUTDOOR SPORTS

7133 HWY 47

UNION. MO 63084 US

Phone (H)

(636)-583-0702

Fax

(636)-583-0712

**Email** 

Phone (W)

Reported		- 125 - 125	Found
M993	FIRES WHEN TAKEN OFF SAFE	M102	BALANCE OF FIREARM IS NEEDED 7
M994	SEND TO PRODUCT SERVICE FOR INSPECTION	M123 M176	FORWARD TO PRODUCT SERVICE FOR RETURNED FOR RECALL/UPDATE
1	1101 Le11011		

<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity</u>	<u>Quantity</u>	<u>Quantity</u>	<u>Warranty</u>
		<u>Needed</u>	From Inv	From Kit	<u>(Y/N)</u>
Part					
F91469	600 TRIGGER ASSB	1	1	0	Y
Part	Total:	1	1	0	
Service					
4000294	GR-CHECK TPA	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119	GR-TEST	1	1	0	Y
Service	Total:	2	2	0	!

**ProblemNotes** 

We could not duplicate customers concern. We did find the adjusting screws altered. Trigger never updated. Replace trigger assm. update.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date