

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL
FPS

CUSTOMER ORDER NO.
5816

DATE RECEIVED 01/21/91	DATE OPENED 01/29/91	DATE CODE CC 4-82	SERIAL NUMBER B6382158	MODEL AND GRADE 700 25-06 BDL	ORDER R 91-02900
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS	

FROM:

DANNYS PAWN & SPORTING
300 S BROADWAY
MCALLEN TX 78501

SHIP TO:

DANNYS PAWN & SPORTING
300 S BROADWAY
MCALLEN TX 78501

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 2-6	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

rifle sometimes fires when bolt is closed

MAIN FAULT

Cannot duplicate complaint. However, trigger assembly contaminated with a sticky substance; internal trigger parts are not moving freely. In addition, trigger assembly has been improperly adjusted outside factory - 1) insufficient over-travel 2) insufficient sear engagement. Trigger pull O.K. at 4 pounds - reset lift c.k. at 2012". Rifle has not been properly maintained.

Send repair quote for new trigger assembly but 1/2 normal price as gesture of good-will.

REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE