

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R92-10723ITALY
CUSTOMER ORDER NO.
E53974

L/FLOOR PLATE, SCREWS

DATE RECEIVED
1/20/92DATE OPENED
04/28/92DATE CODE
PB 6-81SERIAL NUMBER
B6320340

NEW SERIAL NUMBER

MODEL AND GRADE
700 7MM-08

VAR

ACCESSORIES
L/MAG BOX L/WOOD

L/FOLLOWER

L/MAG SPRING SCOPE BASE

FROM
ENGLISHTOWN SPTG GOODS CO
38 MAIN ST
ENGLISHTOWN NJ 07726SHIP TO:
ENGLISHTOWN SPTG GOODS CO
38 MAIN ST
ENGLISHTOWN NJ 07726

CUST NO: 003483 C.O.D.

ACCOUNT NUMBER
63103

ACCOUNT NUMBER N/C

WRITE

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

CONDITION
NEW
LIGHTLY WORN
WORN
VERY WORN
UNREPAIRABLE
MARRIED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
COLE	A1	B1				
RIGGER GROUP		B2			E1	F1
OLT ASSY		B3			E2	F2
ARREL ASSY		B4		D1	E3	F3
EC ASSY		B5		D2	E4	F4
OOD			C1	D3	E5	F5
ETAL			C2			

IN FAULT
Trigger Assy adjusted outside factory, unable to readjust.
Trigger assembly has been adjusted to point firing pin at fall when trigger is pulled - no over travel at all. Cannot duplicate complaint as rifle will not fire at all.

RTG
26345 Trigger Assy.
Quote for new trigger assembly at \$ normal cost, as gesture of good-will.
Warn customer about adjusting trigger.
Test w/ spare parts.

REPAIRMAN DE	PROOF	CLEAN	TEST ✓	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS02137