



# TRACKING DOCUMENT

Repair Order Number



|   |  |  |
|---|--|--|
| <b>Repair Order Number</b><br>RE00057971  | <b>Description/Serial Number</b><br>E6786115 | <b>Repairman -</b> Bruce Travis  |
| <b>Account # - R-</b>   | <b>Model 700 Center Fire Caliber: 7MM</b>    | <b>Date Received -</b> 12/20/2002  |
|   | <b>MAG ADL SYNTHETIC</b>                     | <b>Estimate Date -</b>   |
|   |  | <b>Current Date -</b> 12/31/2002   |
| <b>Customer</b><br>BILL EASLEY<br>BLISS MURSKI SALES<br>8518 N E 129TH STREET<br>JONES. OK 73049 US |  | <b>Return To</b><br>BILL EASLEY<br>BLISS MURSKI SALES<br>8518 N E 129TH STREET<br>JONES. OK 73049 US |
| <b>Phone (H)</b> (405)-771-3516   | <b>Fax</b> (405)-771-4054                    |  |
| <b>Phone (W)</b>  | <b>Email</b> bill.easley@att.net             |  |

| Problems |  |       |                              |
|----------|--|-------|------------------------------|
| Reported |  | Found |                              |
| M123     | FORWARD TO PRODUCT SERVICE<br>FOR INSPECTION | M123  | FORWARD TO PRODUCT SERVICE F |

| Repair                |                               |                            |                              |                              |                           |
|-----------------------|-------------------------------|----------------------------|------------------------------|------------------------------|---------------------------|
| <u>Material #</u>     | <u>MaterialDesc</u>           | <u>Quantity<br/>Needed</u> | <u>Quantity<br/>From Inv</u> | <u>Quantity<br/>From Kit</u> | <u>Warranty<br/>(Y/N)</u> |
| <b>Part</b>           |                               |                            |                              |                              |                           |
| F26345                | 700 TRIG ASSB RH              | 1                          | 1                            | 0                            | Y                         |
| <b>Part Total:</b>    |                               | 1                          | 1                            | 0                            |                           |
| <b>Service</b>        |                               |                            |                              |                              |                           |
| 4000104               | ARMS SERV SHIPPING & HANDLING | 0                          | 0                            | 0                            | Y                         |
| 4000119               | GR-TEST                       | 1                          | 1                            | 0                            | Y                         |
| <b>Service Total:</b> |                               | 1                          | 1                            | 0                            |                           |

|  |              |              |             |               |                |
|--|--------------|--------------|-------------|---------------|----------------|
| <b>ProblemNotes</b> upon receipt we could not duplicate the reported concern - during the exam it was noted that a small metal chip is visible inside the trigger pin hole of the housing.replace trigger assm at no charge. |              |              |             |               |                |
| <b>Repairman</b>   | <b>Proof</b> | <b>Clean</b> | <b>Test</b> | <b>Target</b> | <b>Pattern</b> |
| <b>Gallery Tester</b>  | <b>Date</b>  | <b>Date</b>  | <b>Date</b> | <b>Date</b>   | <b>Date</b>    |