

Repair Order Number



Repair Order Number RE00057615	Description/Serial Number B6777163	Repairman - Herb Brown Date Received - 12/23/2002
Account # - R-	Model 700 Center Fire Caliber: 270 MR W/ SCOPE	Estimate Date - 12/17/2002 Current Date - 1/7/2003
Customer BARRY ETLICHER E6618 COUNTY RD V  RIDGELAND. WI 54763 US	Return To BARRY ETLICHER E6618 COUNTY RD V  RIDGELAND. WI 54763 US	
Phone (H) (715)-949-1190 Phone (W)	Fax Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123 M178	FORWARD TO PRODUCT SERVICE FOR TRIG ADJ SCREWS RESET, CANNOT

Repair					
Material #	Material Desc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
<b>Part</b>					
F22040	700 FIRING PIN ASSB L/A	1	1	0	N
F26345	700 TRIG ASSB RH	1	1	0	N
<b>Part Total:</b>		<u>2</u>	<u>2</u>	<u>0</u>	
<b>Service</b>					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000118	GR-CLEAN	1	1	0	N
4000119	GR-TEST	1	1	0	N
4000294	GR-CHECK TPA	1	1	0	Y
<b>Service Total:</b>		<u>3</u>	<u>3</u>	<u>0</u>	

Condition	REC'D W/ MINOR WOOD DINGS.				
Problem/Notes	Action and trigger assm covered with sticky substance. Trigger adjusting screws re-set. Replace trigger assm. at spec. price. Forward end of firing pin altered.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date