

To whom this may concern

I own this Remington Model 700, 300 Ultra Mag Serial # E6780852. I purchased the gun April 7<sup>th</sup> 2003. You'll see a copy of the receipt in the box with this letter.

The problem that I had with the gun was upon releasing the safety the gun unexpectedly Fired. This shouldn't have happened! Because of this I am very leery of this gun on whether it will do the same thing again. Please examine the gun, and see if you can get it to duplicate what happened to me. The gun has only been fired 5 times; the 5<sup>th</sup> time was when the gun fired upon removal of the safety.

I did some research on the rifle before I bought it. I firmly believe that the Model 700 is one of best guns ever made. Not only for it's accuracy, but safety too. I hope you find something wrong with it so the problem can be solved.

I can be reached by phone at two numbers. One is a work phone (616) 527-5555 ext. 21, or My home phone (616) 522-9252.

Thank you  
Raymond Erickson

12/30/03 Upon receipt we could duplicate the reported  
Concern - Upon dis. reveal a small metal welding  
chip along side of the trigger & small rusting area on  
trigger pin hole. Replace the compact trigger assembly at  
no charge. Check  
2/30/05

Serial  
Number:

**E6780852**

Model: **700**



**RE00074472**