

Serial
Number:

A6609118

Model: 700



RE00014025

20 July, 2000

Remington Arms
Attention: Arms Service
14 Hoefler Ave.
Ilion, NY 13357

Dear Remington Arms:

I am sending my Remington Arms Model 700, 30-06, serial # A6609118 back, for repairs to the trigger mechanism. The trigger has a delayed lock time. You can pull the trigger and it will not fire sometimes for 1-2 seconds. The trigger mechanism also fired when I moved the safety from safe to fire.

I do not feel comfortable from a safety standpoint and would like for you to take a look at this rifle. I would appreciate anything you can do to make this rifle safe and usable. Please feel free to contact me at work (540) 261-9829 or home (540) 261-2458 for any information that may speed up the process.

Sincerely,

Randy Elliott

Randy Elliott
1654 Birch Ave.
Buena Vista, VA 24416

*Replace trigger assembly at
1/2 MSP # 26345*

9/19/00 Trigger has a delayed lock time.

*Upon receipt trigger components seized up from being
exposed with a known heavy sticky substance. Rifle poorly maintained
Action & barrel also covered with the substance.*