

File Number:	16243		Arms Service number:	28100	
Last Name:	EUBANK'S WESTERN CORNER			First Name:	
Street:	122 S MAIN		City:	LINDSAY	
State:	OK	Zip:	73052	Home Ph:	
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI	PD	P	S
Concern Code:	1008				
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND	
Settlement Detail:	INSTALL NEW TA AT SPECIAL PRICE			Settlement Amount:	\$0.00
Date Opened Rem:	6/4/01	Date Opened by P/S:	6/4/01	Caliber:	3006
Date of Incident:		Date Closed:	6/5/01	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	6750980	Date Code:	PY
Date Mfgd:	6/1/74				
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Obsolete:	☐				
Custody:		Comments:	Gun fires when bolt shuts concern - could not duplicate - TA coated with sticky residue, sear cam barely moves, trigger slow regaining, bolt release sticks - Not properly maintained - Install new TA at 1/2 normal charges.		
Time of Modification:	3:47:40 PM				
Date of Modification:	6/4/01				