

From:
Patrick Erickson
5593 Little Bass Lake Road NE
Bemidji, MN 56601

Ship to:

Remington Arms Company, Inc.
Attn: Arms Services Division/Repairs
14 Hoefler Avenue
Ilion, NY 13357

Just Call RI
11/76

Please replace trigger assembly to new style (I want to be able to unload without putting the safety on fire). This is my brother's gun (ser A6352225 number model 700 LH caliber 30-06) and he to has had it fire when removing the safety about 2 years ago. I told him I had my rifle modified and he wanted his done as well. The repair order from my gun was RE00018036.

Thanks
Patrick Erickson
5593 Little Bass Lake Road NE
Bemidji, MN 56601
(218)759-0539

2/21/01 *Replace w/ trigger assembly new style.*
has fired when removing the safety 2 yrs ago

Action & trigger assembly dirty, all 3 adj screws on
trigger housing have been re-set.

Replace the trigger assembly complete
with Non Bolt Lock current
style at 1/2 MSP &
clean action *GO ahead*

Serial
Number:

A6352225

Model: **700**



RE00023343