



## TRACKING DOCUMENT

Repair Order Number



<b>Repair Order Number</b> RE00054988	<b>Description/Serial Number</b> ML203162	<b>Repairman -</b> Herb Brown
<b>Account # - R-</b>	<b>Model</b> 700ML <b>Center Fire</b> <b>Caliber:</b> 50	<b>Date Received -</b> 11/1/2002
<b>Customer</b> DAN EVERETT 3541 GRIER NURSERY RD STREET. MD 21154 US		<b>Estimate Date -</b> <b>Current Date -</b> 11/4/2002
<b>Phone (H)</b> (410)-879-9930 <b>Phone (W)</b>		<b>Return To</b> DAN EVERETT 3541 GRIER NURSERY RD STREET. MD 21154 US
	<b>Fax</b> <b>Email</b>	

Reported		Problems Found	
M992	FIRE WHEN SAFE MOVED	M123	FORWARD TO PRODUCT SERVICE F

Material #		MaterialDesc		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
F99294		700 ML SS TRIG ASSB		1	1	0	Y
Part Total:				1	1	0	
Service							
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
Service Total:				0	0	0	

<b>Condition</b>	Rec'd w/rust in loading ramp.				
<b>Problem/Notes</b>	Hammer cracked through at pin hole- bent out of position. Replace trigger assm. and clean rifle at no charge. Working parts rusty. Note clean after each use.				
<b>Repairman</b>	<b>Proof</b>	<b>Clean</b>	<b>Test</b>	<b>Target</b>	<b>Pattern</b>
<b>Gallery Tester</b>	<b>Date</b>	<b>Date</b>	<b>Date</b>	<b>Date</b>	<b>Date</b>