

*Setup file*

REPAIR GUN INQUIRY FUNCTION: E (N)EXT (P)REV (I)NQ (E)XACT 07/25/90  
ENTER REPAIR NUMBER -----> 9018689 16 07 30

FROM: (CUST NUM: 025562 ) EGGERT MODEL: 700  
EGGERT, TROY GA/CAL: 0030-06  
19319 OXFORD STREET TYPE: BDL  
ACCESSORIES: W/STUDS  
HARD CASE

ELK RIVER MN 55530  
SHIPPED TO:

612-493-2749

DATE CODES: PF 6-85  
OTHER ACCESSORIES:

COMMENTS: HARD CASE RETURNED 7-25-90

DATES:		TO	FROM	
RECEIVED	06 25 90	GALLERY	07 16 90	07 17 90 ENTERED BY: JJM
OPENED	07 02 90	PROD SERV	00 00 00	00 00 00 REPAIRMAN: RF
ESTIMATED	07 13 90	TAG GUNS	00 00	00 00 00 TYPIST:
PROMISED	00 00 00	REJECTED	00 00	00 00 00 CORRESPONDENT:
REPAIRED	00 00 00	CASH RECEIVED:	\$	0.00
SHIPPED	07 23 90			
BILL TYPE	N/C			

PF1 = VIEW DETAIL

REPAIR NUMBER: 9018689 NO CHARGE EST/LETTER LSTD 07/25/90  
CUSTOMER NAME: EGGERT, TROY 16 07 41

REQUEST: MISFIRED, SCRATCHED AND MARRED BOLT. STOCK SCRATCHED.  
MAIN FAULT: FRONT GUARD SCREW TOO LONG CAUSING BOLT NOT TO FULLY CLOSE.  
BOLT SHOWS ABNORMAL WEAR FOR CONDITION OF RIFLE, WE WILL  
REPLACE IT. WE CANNOT BE RESPONSIBLE FOR A STOCK SCRATCHED  
OUTSIDE OF OUR CONTROL.

PARTS: \$ 0.00 1 92897 BOLT ASSEM (BDL 270 - 30-06 MAX)  
LABOR: \$ 0.00 CHAMBER EXTREMELY RUSTY, MUST BE KEPT CLEAN AND LIGHTLY  
\$ 0.00 OILED  
\$ 0.00 POLISH CHAMBER  
\$ 0.00 ADJUST FRONT GUARD SCREW  
\$ 0.00 SEND OWNERS MANUAL  
\$ 0.00 PROOF, CLEAN, TEST

CLEAR = RETURN  
NO MORE DATA AVAILABLE FOR THIS REPAIR