

RECEIVING AND ESTIMATING REPORT

COMMENTS

ATTN JIM STEKL W/J.L. STARK BBL, STOCK NOT OUR
MFG. W/ 1 STUD

INITIAL CUSTOMER ORDER NO.

FJB

DATE RECEIVED
10/19/90

DATE OPENED
10/24/90

DATE CODE

SERIAL NUMBER
6253567

MODEL AND GRADE
700 300 WIN MAG

ORDER
R 90-278

ACCESSORIES SCOPE BASE

FROM:

LES FREER
8928 SPRING BRANCH DR.
BLDG B-1
HOUSTON TX 77080

SHIP TO:

LES FREER
8928 SPRING BRANCH DR.
BLDG B-1
HOUSTON TX 77080

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☒ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

Rifle fired when bolt was closed

MAIN FAULT

1) trigger assembly improperly adjusted outside of factory. 2) engagement surface on connector of rear safety arm broken — probably from blown primer. Firing pin is rounded & bolt face is gas cut; the breechage resulted from the little rear engagement coupled with primer leakage. Safety lever has been broken off & re-cut. As received, rifle would not cock because of broken rear-connector surface. Trigger rear surface & firing pin had been filed outside of factory.

Strictly as a gesture of good-will, replace trigger assembly and firing pin assembly at no-charge.

Adjusted trigger pull to 3 1/2 pounds per customer request. (Phone call 11/7/90)

11/7/90

Product Service is keeping trigger & firing pin.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD4925 REV. 7

PS02293