

RECEIVING AND ESTIMATING REPORT

INITIAL ☒ ORDER NO.		COMMENTS ATTN JIM STEKL W/J.L. STARK BBL, STOCK NOT OUR MFG. W/ STUD (96) 64	
DATE RECEIVED 10/19/90	DATE OPENED 10/24/90	DATE CODE	SERIAL NUMBER 6253537
ACCESSORIES SCOPE BASE		MODEL AND GRADE 700 300 WIN MAG	ORDER R 90-27819

FROM: LES FREER 8928 SPRING BRANCH DR. BLDG B-1 HOUSTON TX 77080	SHIP TO: LES FREER 8928 SPRING BRANCH DR. BLDG B-1 HOUSTON TX 77080
--	---

ACCOUNT NUMBER	ACCOUNT NUMBER N/C 059001	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED 11-12-90	VIA UPS
----------------	------------------------------	---	------------	-----------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

ITEM CONDITION:	☐ NEW	☐ SLIGHTLY WORN	☐ VERY WORN	☒ MISUSED	☐ MARRED
CUSTOMER'S REQUEST	Rifle fired when bolt was closed				

1) trigger assembly improperly adjusted outside of factory. 2) engagement surface on connector of rear safety cam broken - probably from blow primer as firing pin is seated & bolt firing gas cuts. This damage resulted from the little rear engagement coupled with primer blowback. Safety lever broken top of re-coiled also. As received, rifle would not cycle because of broken rear connector surface. Top rear surface of firing pin had been filed outside of factory.

21345 Trigger assembly properly adjusted and firing pin assembly 22040 firing pin assembly with no change.

Chamber light on Sammi handling and adjust trigger pull to 3 1/2 pounds per chamber agent. (View call 11/1/90)

belt plugs for bench check for function only as barrel not of our manufacture

ready to ship

REPAIRMAN GHT	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE		