

TRIG Pull 5#

SEAL Lin .008

Some Sealant Missing

Engagement Adjusted

Outside Factory

As Gesture Or Good

Will Replace TRIG Assy