

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-0997

INITIAL CUSTOMER ORDER NO.

BOTTOM HALF OF MOUNTS ONLY

STEKL

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

MTN

04/07/92

04/15/92

AG 3-86

B6778078

700 270

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

FURLONG, JIM
RD 2 SILVER CREEK RD
JOHNSONBURG

PA 15845

SHIP TO:

FURLONG, JIM
RD 2 SILVER CREEK RD
JOHNSONBURG

15845

CUST NO: 060923 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

4/28/92

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

S1

TRIGGER GROUP

BOLT ASSY.

B3

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Complaint was duplicated; also, at times the firing pin followed down as the action was closed. Disassembly of the trigger revealed that the trigger assembly had been improperly adjusted at the factory - Trigger pull was only 2 1/2 pounds, and the adjustment screw had been backed out so far that there was no retention spring at all.

Sear lift, 0.12"

PARTS

COMMENTS

Offer to re-adjust present trigger assembly, or, to install new trigger assembly at normal cost, as a gesture of goodwill, if that will provide me confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATT

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV

PS02315