

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-06062

DATE RECEIVED	CUSTOMER ORDER NO.	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
02/18/92	038326	02/26/92	BC 1-82	B6370740		700 243 BDL
ACCESSORIES W/STUDS SCOPE BASE L/REAR SIGHT						

FROM:

FLOYDS SPORTING GOODS
4359 MERLE HAY RD
DES MOINES IA 50310

SHIP TO:

FLOYDS SPORTING GOODS
4359 MERLE HAY RD
DES MOINES IA 50310

CUST NO: 001731 ILION

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					3-16	UPS

- GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	Fired on bolt closing				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT:

Rifle can be made to prove if bolt is done properly. Parameters of rifle revealed that trigger assembly has been improperly adjusted to factory - accuracy is missing from all adjustment screws. 1) trigger pull measured 1 1/2 pounds (will follow our minimum specification) 2) sear engagement is insufficient

Trigger pull 1 1/2 pounds; sear lift .011"

PARTS

COMMENTS

Offer new trigger assembly at 1/2 normal cost as a gesture of customer good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
BWT					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFF COPY

RD6925 REV. 8/91

PS02335