

RECEIVING AND ESTIMATING REPORT

COMMENTS

*Product Service*ORDER
R 95-01981

INITIAL FPS	CUSTOMER ORDER NO.				
DATE RECEIVED 01/06/95	DATE OPENED 01/17/95	DATE CODE EO 10-94	SERIAL NUMBER D6824636	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN ADL
ACCESSORIES W/STUDS					

FROM:

FUDGE, DAVID D.
219 LOBLOLLY DRIVE
DURHAM

NC 27712

SHIP TO:

FUDGE, DAVID D.
219 LOBLOLLY DRIVE
DURHAMNC
27712

CUST NO: 112860 C.D.L.

ACCOUNT NUMBER	ACCOUNT NUMBER NIP 039015	WRITE ☐	FROM DATE	ESTIMATED 2-15	VIA UPS
GUN CONDITION	<i>[Signature]</i> 2/15				REPAIR CHARGE
☒ NEW					EXCISE
☒ LIGHTLY WORN					TAX
☐ WORN					INSURANCE
☐ VERY WORN					UPS
☐ UNREPAIRABLE					PARCEL POST
☒ MARRED					TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		<i>Bolt closes hard on live rounds</i>				F1
BOLT ASSY.		B3		E2		F2
BARREL ASSY.		<i>Fail when closing bolt</i>				F3
REC. ASSY.		B5		E4		F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Mfg. 10/94 Only way gun could be made to fire as rec'd was with safe off and trigger pulled. Hard bolt closing may be ammo related. Replace extractor, polish chamber. Customer may have inadvertently contacted trigger when closing the bolt.

PARTS	Extractor	COMMENTS					
		<i>trig. pull measured 4 3/4 LBS as rec'd. Sear lift was .0165</i>					
		<i>Sear engagement was .018</i>					
		<i>NO incident case returned</i>					
		<i>Extractor out of position as rec'd.</i>					
		<i>Bolt face slightly etched from leaky primer pockets</i>					
		<i>Headspace OK as rec'd</i>					
		REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
		GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PS02340