

Remington®



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

April 9, 1991

Mr. Fred Fuller, Sr.
P.O. Box 817
Bowie, TX 76230

Dear Mr. Fuller:

Reference is made to your recent letter regarding the accidental discharges you experienced while using your Model 700 BDL 7mm Rem. Mag caliber rifle, serial number 6773921.

We were indeed sorry to learn of your having a problem of any kind with one of our products.

Generally, the type of problem you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or from inadvertent contact with the trigger when the safety was in the "fire" position.

We would very much like to have the opportunity to examine your complete rifle so that we can evaluate the cause of your problem. If you are willing to permit us to examine the gun at our laboratory here in Ilion, NY, we will be glad to promptly advise you of our findings.


If this is agreeable to you, please, at your convenience, return the rifle via UPS, transportation charges C.O.D. to:

Remington Arms Company, Inc.
Attn: J.A. Stekl, Product Service
14 Hoefler Ave.
Ilion, NY 13357

Please be sure to mark the two (2) butt ends of the outside of the package "STEKL" to expedite handling

Thank you for bringing this matter to our attention, and for affording us this opportunity to be of service to you.

Sincerely,

A handwritten signature in cursive script, appearing to read "J.A. Stekl".

J.A. Stekl, Specialist
Product Services

JAS:tp