

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL CUSTOMER ORDER NO.

LCS

DATE RECEIVED

01/07/91

DATE OPENED

01/10/91

DATE CODE

EH 10-87

SERIAL NUMBER

C6203755

MODEL AND GRADE

700 30-06 BDL

ORDER

91-01021

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

FRANK'S SPORT SHOP
2244 86TH ST.
BROOKLYN

NY 11214

SHIP TO:

FRANK'S SPORT SHOP
2244 86TH ST.
BROOKLYN

NY
11214

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

TARP

PROM. DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"Customer claims safety not working: Fails in closing bolt"

MAIN FAULT

*Tugger assembly rusted from unknown source - internal
tugger parts not moving freely nor correctly.*

PARTS

*Replace tugger assembly at no charge,
at gesture of good will.*

REPAIRMAN

JTB

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

RD6925 REV. 7/90

PS02418