

RECEIVING AND ESTIMATING REPORT

CUST NO: 048525 C.O.D

STELCO

AL	CUSTOMER ORDER NO.	COMMENTS					
M							
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
7/30/91	09/04/91	XC 12-82	B6432968	700	22-250	BDL/VAR	R 91-17382
ESSORIES		W/STUDS					

TO:	SHIP TO:
FISHER, WILLIAM H RTE 1 STAR RT 679 BOX 417 FINCASTLE USA	FISHER, WILLIAM H RTE 1 STAR RT 679 BOX 417 FINCASTLE USA
VA 24090	VA 24090

QUANTITY	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					9/20/91	UPS

R CHARGE						TAX	INSURANCE	UPS	PARCEL POST	TOTAL
----------	--	--	--	--	--	-----	-----------	-----	-------------	-------

CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

OWNER'S REQUEST: "This gun fired when loading. It won't stay locked part of the time. I think there is a problem with the trigger assembly."

FAULT: Trigger assembly has been improperly adjusted outside of factory - cannot missing from adjustment screws. 1) Trigger pull mechanism only 1 pull - trigger return spring force is non-existent. Firing pin will follow-down on bolt closing because of above condition 2) excessive over-travel. Seen left - 0.125"

Send quote for new trigger assembly at 2.0000 price, as good-will gesture.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
AS					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE